




EIBENSTOCK
Elektrowerkzeuge

Ersatzteilliste

EHD 1500



EHD 1500 - 230 V

03E11000

No.	Description	Order No.	Pcs	No.	Description	Order No.	Pcs
1	connecting cable	80600470	1	28	grooved ball bearing 6203 2RS	80410130	1
2				29	work spindle	73110420	1
3	anti parasite condenser	73E31305	1	30	axial bearing AX 513	80420031	1
4	pair of handle halves	80900217	1	31	clutch shaft	73116500	1
5	cable grommet	83000004	1	32	needle sleeve HK 1210	80420131	1
6	switch	80600512	1	33			
7	pt-screw 40x25	80201412	3	34	spring washer 28/12,2x1,25	80200714	6
8	wire locking flange	85000020	1	35	brass washer	85000040	1
9	pt-screw 40x12	80201413	2	36	driving washer	73116496	1
10	pt-screw 50x30	80201411	2	37	notched pin plug 4x12	80200582	1
11	o-ring 72x2	83000182	1	38	clutch wheel	73116550	1
12	grooved ball bearing 608 2Z	80410011	1	39	cylinder bearing Getro Typ 1210 T	80420241	1
13	o-ring 22x2,5	83000036	1	40	spring washer 25/12,2x0,9	80200710	1
14	brush holder	80201196	2	41	hexagonal nut BM10/1	80201007	1
15	carbon brush 6,3x10x18	80700013	2	42	clutch complete	73116493	1
16	self tapping screw CM4x12	80201180	4	43	needle sleeve HK 0810	80420110	1
17	lock washer B4	80201385	4	44	end shield of gearing	73E11610	1
18	motor housing	80900153	1	45	rotor complete	73E11100	1
19	self tapping screw HC 3,9x70	80201265	2	46	stator complete	73116150	1
20	air guiding ring	80900148	1	47	PCB / circuit board	73E1128U	1
21	locking ring 28/1,2	80201333	1	48	self tapping screw HC 2,9x13	80201252	2
22	grooved ball bearing 6001 2Z	80410031	1	49	fastener	80601153	1
23	worm seal	73110125	1	50	pt-screw 50x40	80201439	4
24	spindle wheel	73110430	1	51			
25	fitting washer 15/22x0,2	80200504	1	52			
26	grooved ball bearing 6003 2RS	80410043	1	53	side handle	73E11695	1
27	gearbox housing	73E11400	1				